

WELL COMPLETION REPORT
3/71

41 29 59

LAKE CARMEL

#300 73 42 07

PUTNAM COUNTY DEPARTMENT OF HEALTH
Division of Environmental Health Services
COUNTY OFFICE BUILDING - CARMEL, NEW YORK

This report is to be completed by well driller and submitted to County Health Department together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality before certificate of construction compliance is issued.

REPORT MUST BE SUBMITTED WITHIN 30 DAYS OF WELL COMPLETION

P1056

OWNER	NAME McGlasson Builders (No. & Street)		ADDRESS Main Street, Carmel, NY (Town)		(Lot Number)
LOCATION OF WELL	South Lake		Carmel		32
PROPOSED USE OF WELL	<input checked="" type="checkbox"/> DOMESTIC	<input type="checkbox"/> BUSINESS ESTABLISHMENT	<input type="checkbox"/> FARM	<input type="checkbox"/> TEST WELL	780 L
	<input type="checkbox"/> PUBLIC SUPPLY	<input type="checkbox"/> INDUSTRIAL	<input type="checkbox"/> AIR CONDITIONING	<input type="checkbox"/> OTHER (Specify)	
DRILLING EQUIPMENT	<input type="checkbox"/> ROTARY	<input checked="" type="checkbox"/> COMPRESSED AIR PERCUSSION	<input type="checkbox"/> CABLE PERCUSSION	<input type="checkbox"/> OTHER (Specify)	
CASING DETAILS	LENGTH (feet) 21	DIAMETER (inches) 6	WEIGHT PER FOOT 19	<input checked="" type="checkbox"/> THREADED <input type="checkbox"/> WELDED	DRIVE SHOE <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
				WAS CASING GROUTED? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
YIELD TEST	<input type="checkbox"/> BAILED	<input type="checkbox"/> PUMPED	<input checked="" type="checkbox"/> COMPRESSED AIR	HOURS 8	G.P.M. 5
WATER LEVEL	MEASURE FROM LAND SURFACE—STATIC (Specify feet)		DURING YIELD TEST (feet)		Depth of Completed Well in feet below Land surface:
	MAKE		Total Drawdown		305
SCREEN DETAILS					LENGTH OPEN TO AQUIFER (feet)
	SLOT SIZE	DIAMETER (inches)	IF GRAVEL PACKED	Diameter of well including gravel pack (inches)	GRAVEL SIZE (inches) FROM (feet) TO (feet)

DEPTH FROM LAND SURFACE		FORMATION DESCRIPTION
FEET	to FEET	
1	305	Rock

Sketch exact location of well with distances, to at least two permanent landmarks.

RECEIVED

JAN 31 1983

PUTNAM COUNTY
DEPT. OF HEALTH

If yield was tested at different depths during drilling, list below	
FEET	GALLONS PER MINUTE

DATE WELL COMPLETED 12.20.82	DATE OF REPORT 12.20.82	WELL DRILLER (Signature) <i>W. Van B...</i>
---------------------------------	----------------------------	--